

# TECHNICAL BULLETIN

NO. 103

SUBJECT: DATAPRODUCTS PRINTER INTERFACE ADAPTER

DATE: MARCH 11, 2014

TO: TECHNICAL MANAGERS OF FLIGHT SIMULATOR HARDWARE

PAGES: 1 OF 1

CLASSIFICATION:  ACTION REQUIRED

TROUBLESHOOTING

PRODUCT APPLICATION

## PROBLEM:

The lineprinter that is used with the simulator may be out of date and difficult to maintain or be expensive to operate. Because the printer interface connection may be obsolete or rare, a replacement printer may not be available.


## SOLUTION:

Attach Model DC interface adapter to the print cable connector, then use the new output cable to connect to a wide variety of modern printers. Also, you may choose to record to a flash memory SD Card Recorder or send print data direct to a PC serial COM Port.

This information is based on the Model DC installation success at several airlines over the last five years.

## TO REPLACE OLDER LINEPRINTERS:

- Genicom
- Printronix
- Hitachi
- C.Itoh
- Dataproducts
- Fujitsu



## CONTACT:

Rick Hoffman, Photologic Ltd. Area: Toronto, Canada

DCADAPTER.DOC